Important Information

On some PCs, when iPod is connected with the USB cable, it's possible that your PC will not complete the start-up process. If you encounter this, simply disconnect iPod from the PC by lifting it out of the iPod Dock or disconnecting the USB cable. The start-up process will then complete. Once the PC start-up process is complete, reconnect iPod for normal operation.

If you are experiencing this issue on an HP or Compaq PC, please visit the HP Support Web site at http://www.hp.com/support and go to your product support page for the latest BIOS update for your PC. If you are experiencing this issue on any other brand PC, check your PC manufacturer's Web site for any available PC software or BIOS updates.

© 2004 Hewlett-Packard Development Company, L.P. All rights reserved.

iPod is a trademark of Apple Computer, Inc., registered in the U.S. and other countries. For legal or rightholder-authorized copying only. Don't steal music.

HP supports lawful use of technology and does not endorse or encourage the use of our products for purposes other than those permitted by copyright law.

Printed in China 034-2787